INFO :

25X1A8a

25X1A2g **2684 (IN 12384)** 

1447Z 16 JAN 57

**ROUT LNE** 

CITE:

25X1A2g

25X1A2g 25X1A2a

25X1A2g

REF:

TO:

A.

7542 (OUT 60051)

B. 2654 (IN 12277)

25X1A2e

4.

- 2. RE REF A PARA ONE AND TWO NORMAL PROCESSING TRIED WITH TEMPERATURE 155-160F AT 6 TO 7 FT PER MINUTE WITH SIDE PANELS ON AND OFF. RESULTS UNSATISFACTORY.
- 3. RE REF PARA THREE AND FOUR. SOLUTIONS AT ALL TIMES FRESHLY MIXED. LEADER REFERRED TO IN REF B WAS ACTUALLY CLEARED FILM.
  - 4. ADDITIONAL TESTS AS FOLLOWS:

25X1A2e

- A. TEST ONE. FILM PROCESSED ACCORDING TO SOP. RUN
  THROUGH NEW A-10 A DRYER. FILM EQUALLY TACKY, BUT RESULTS NEARLY
  SATISFACTORY PROBABLY DUE TO DIFFERENCE IN FEED AND TAKE UP.
- B. TEST TWO. FILM PROCESSED ACCORDING TO SOP. RUN THROUGH A-14 DRYER AT NORMAL TEMPERATURE WITH AND WITHOUT SIDE PANELS. RESULTS UNSATISFACTORY.
  - C. TEST THREE. FILM PROCESSED IN AEROSOL, DEVELOPER, SHORT-

Approved For Release 2000/08/26 - CLA-ROPA18 007504000400080155-7

## Approved For Release 2000/08/26/FCIA IRDINS/08/00750A000400080155-7

DATE : 16 JAN 57

SECRET

PAGE 2

25X1A2g

2684 (IN 12384)

STOP, SODIUM THIOSULFATE CRYSTALS, POWDERS FIXING BATH HARDENER AND 15 MINUTE WASH OMITTING PERMAWASH. RESULTS VERY SATISFACTORY.

- D. TEST FOUR. FILM DEVELOPED SOP INCLUDING DOUBLE STRENGTH HARDENER BUT OMITTING PERMAWASH. RESULTS SATISFACTORY.
- E. TEST FIVE. REPEAT OF TEST FOUR USING SINGLE STRENGTH HARDENER. RESULTS EQUALLY SATISFACTORY.
- 5. OMITTING PERMAWASH CAUSES DEFINITE DIFFERENCE IN FEEL OF FILM, GIVES FILM "GRIP". IT APPEARS THAT PERMAWASH BASIS OF PROBLEM. MORE TESTS TO FOLLOW TOMORROW. PLEASE COMMENT. END OF MESSAGE